

SECRET

OUT 66937

1

SECRET 312046Z JAN 69 CITE [] 5575

25X1

31 JAN 69 21 025X1

SUBJ: EVALUATION OF GLASS LAMP MISSION G-067.

1. IMAGE QUALITY: THE OVERALL IMAGE QUALITY OF THIS MISSION IS GOOD. THE IMAGE QUALITY VARIES ACROSS THE FORMAT, WITH THE BETTER IMAGERY BEING NEAR THE NON-DATA CHAMBER END OF THE FORMAT. THE GROUND RESOLUTION AND INTERPRETATION SUITABILITY IS GOOD. CLOUD COVER AFFECTS APPROXIMATELY 15 PERCENT OF THE ENTIRE MISSION.

2. MISSION DATA:

A. MISSION G-067, FLOWN ON 28 JANUARY 1969, UTILIZED THE STANDARD "B" CAMERA CONFIGURATION (UNIT NUMBER 10).

B. FILM TYPE 3401 WAS USED THROUGHOUT THE MISSION WITH AN EXPOSURE OF 1/415 AT F/11. THE MATERIAL WAS PROCESSED TO AVERAGE GAMMAS OF 2.12 (LEFT SIDE) AND 2.19 (RIGHT SIDE). PROCESSING WAS ACCOMPLISHED BY THE NAV RECON TECH SUPPCEN.

3. ORIGINAL NEGATIVE:

A. EXPOSURE: ADEQUATE THROUGHOUT THE MISSION.

B. DENSITY AND CONTRAST: GENERALLY MEDIUM.

C. IMAGE DEGRADATIONS:

(1) 9L SIDE: PROCESSING STREAKS ARE APPARENT INTERMITTENTLY THROUGHOUT THE MISSION.

(2) 9R SIDE: FOG PATTERNS, APPARENTLY ASSOCIATED WITH CAMERA START-UP, ARE PRESENT ON FRAMES 1 AND 6.

D. PHYSICAL DEGRADATIONS:

(1) 9R SIDE: ONE HEAT SPLICE AND ONE MANUFACTURING SPLICE ARE PRESENT ON THIS MISSION.

(2) 9L SIDE: TWO HEAT SPLICES AND ONE MANUFACTURING SPLICE ARE PRESENT ON THIS MISSION.

E. AUXILIARY DATA: TITLED FRAME 1 CORRESPONDS TO COUNTER 00000. ALL OTHER DATA RECORDING SYSTEMS FUNCTION PROPERLY.

F. THE LAST TITLED FRAME IS 2503, COUNTER 2502.

4. POSITIVES:

A. PRINTING AND PROCESSING ARE GOOD.

SECRET

END OF MESSAGE

DISTRIBUTION	
FILE	
CABLE SEC.	
PP&R/RD	
SECUR.	
34 TSSG/APSD	✓
PSG/OC	
RRD	
REPRO	
AID	
IEG	
PROD	
SCIEN	
WEST	
EAST	
M&S	
PGM	
IAS	
DIA-XX4	
SPAD	
DIA-AP	
CMX	25X1

ADVANCE CY
SANITIZED
WITH TEXT

SECRET

Group 1
Excluded from automatic
downgrading and
declassification